

APPENDIX B – SITE PHOTOGRAPHS



Entrance into the site from Buchell Road



Grassy section on the southern edge of Erf 2006



Invaded areas



Invaded areas on Erf 2006



Heaps of construction rubble dumped on-site



Footpath through Erf 2006



Invaded areas



Illegal solid waste / building rubble disposal



Acacia cyclops invading the site



Alien plants on site



Illegal dumping of waste on-site



Grassy area and alien invasive vegetation